




Attachment C

Attachment C – Aerial Photo 1971 and 2 June 2009 Photos

 <p>This is an aerial photograph from 1971 showing a landscape with several mine sites. Labels with arrows point to the following features: 'Mine Excavation' (top center), 'Central Mine' (top right), 'Manzanita Mine' (middle right), 'West End Mine' (middle left), 'Cherry Hill Mine' (bottom left), and 'Empire Mine' (bottom right). A winding creek, Sulphur Creek, flows through the center of the image.</p>	<p>Photo 1</p> <p>This is aerial photo taken in April 1971 and was obtain from the County of Colusa. This photo shows earth moving or excavation at Manzanita and Central Mines, and excavation directly west of Central Mine. Also note directly south of Manzanita Mine, Sulphur Creek has at least been partially dammed. Several roads cross Sulphur Creek.</p>
 <p>A ground-level photograph showing two dark, rectangular mine portals in a hillside. A person is standing in the foreground for scale. The date '06-02-09' is visible in the bottom right corner.</p>	<p>This is two of the portals associated with Cherry Hill Mine. This mine is on a hill directly adjacent to Sulphur Creek flood plain. Waste material from this mine would or have been discharged to the Sulphur Creek Flood plain. This picture was taken from that plain looking southwest. Photo was taken by Victor Izzo.</p>
 <p>A ground-level photograph showing a pile of large, angular, light-colored rocks on a dirt bank. The date '06-02-09' is visible in the bottom right corner.</p>	<p>This is a picture of angular rock in the bank of Sulphur Creek. This appears to be mining waste rock because it is not typical stream flood plain deposit. This picture was taken directly south of Manzanita Mine. Photo was taken by Jeff Huggins</p>